

State of Utah DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

June 28, 2012

Kirk Nicholes, Resident Agent Alton Coal Development, LLC 463 North 100 West, Ste. 1 Cedar City, UT 84720

Subject: 2011 Annual Report Review Completion, Coal Hollow Mine, C/025/0005, Task ID

#4069

Dear Mr. Nicholes:

The Division staff has completed the review of the 2011 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed on June 28, 2012.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock Coal Program Manager

1) Haddock

DRH/PWB/sqs Enclosure

Enclosure

c: Price Field Office

O:\025005\WG4069ReviewCompletionLetter.doc



Print Form Submit by Email Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by **March 30, 2012.** During a complete inspection an inspector will check and verify the information.

GENE	RAL INF	ORMATION				÷	
Company Name Alton Coal Developm		ment, LLC		Mine Name	Coal Hollow Mine		
Permit Number C/025/0005					11/08/2015		
Operat	or Name	Alton Coal Develop	ment		Phone Number	+1 (435) 867-5331	
Mailing	Address	463 N. 100 W. Suite	1		Email	knicholes@altoncoal.com	
City		Cedar City					
State		Utah	Zip Code 84721				
					DOGM File Locati	on or Annual Report Location	
	Excess	Spoil Piles	☑ Required☑ Not Required				
	Refu	ise Piles	☐ Required ☑ Not Required				
	Impou	ındments	⊠ Required ☐ Not Required				
Other:							
OPERATO	R COMM	ENTS					
Ponds 1, 1A, 2 and 3 were constructed in the 1st quarter of 2011, certified inspection was completed on February 9, 2011 for the annual. For the second quarter, Excess Spoil Pile and Impoundment Inspections were completed on June 15, 2011. For the third quarter, Excess Spoil Pile and Impoundments inspections were completed on September 30, 2011. Fourth quarter, Excess Spoil Pile and Impoundments inspection were completed on December 15, 2011. Copies of the Excess Spoil pile and Impoundment inspections are included in this submittal.							
REVIEWEI	R COMMI	ENTS 🖂	Met Requirements		Did Not meet Requiremen	nts	
The operator has met the requirements for sediment pond and excess spoil pile inspections and certifications.							

COMMITMENTS AND CONDITIONS

The Permittee is responsible for ensuring annual technical commitments in the Mining and Reclamation Plan and conditions accepted with the permit are completed throughout the year. The Division has identified these commitments below and has provided space for you to report what you have done during the past year for each commitment. If additional written response is required, it should be filed as an attachment to this report.

required, it should be filed as an attachment to this report.
Title: TOPSOIL AND SUBSOIL SALVAGE
Objective: Monitor topsoil and subsoil salvage by suitability criteria and depth described in Appendix 2-1, Table
4-1.
Frequency: During operations
Status: Long term Parameter Keen tells of valuence calvaged stackpilled live bauled
Reports: Keep tally of volumes salvaged, stockpiled, live hauled.
Citation: MRP, Volume 1, Chapter 2, Section 231.100, and Appendix 2-1, pg. 4-2.
Operator Comments
20,100 c.y. of topsoil were removed, all of which were placed in the topsoil Pile 4. 81,370 c.y. of subsoil was placed in subsoil Pile 2. No
topsoil or subsoil was live hauled in 2011. Appendix 2-2 was added to the MRP and all soil analysis added June 30, 2011.
Reviewer Comments Met Requirements Did Not Meet Requirements
Priscilla Burton reviewed this report on 5/4/2012. Appendix 2-2 of the MRP contains the analytical reports for topsoil sampled during construction of the site in 2010. The samples sent for analysis on 3/1/2011 represent the quality of the topsoil stored in Topsoil pile #1 (week 1), #2 (weeks 2 & 3), and #3 (week 4). The topsoil sample sent for analysis on 4/4/2011 represents the quality of the topsoil stored in temporary Topsoil pile #4. The two subsoil samples sent for analysis on 4/4/2011 represent the quality of the subsoil in piles 1 & 2 respectively. See Inspection Report #3082 for the condition of the topsoil and subsoil piles on April 26, 2012.
Tid., PREDATOR CONTROL
Title: PREDATOR CONTROL
Objective: To effectively manage predators and increase the population of birds at the Alton lek.
Frequency: Annually
Status: Ongoing
Reports: Annual summary of work completed to date.
Citation: MRP, Volume 2, Chapter 3, Appendix 3-5 page 13
Operator Comments
Alton Coal Development has entered into a 5 year contract with Wildlife Services (copy submitted as addendum to 3-5 of MRP). The 2011 report from Kevin Dustin, predator control specialist with USDA Wildlife Services, indicates 1,100 poison eggs were distributed with an estimated 1 raven killed for every 4 eggs placed or 275 ravens exterminated. Also, Federal Trappers, trapped or killed 18 coyotes from the Alton area.

Reviewer Comments

Met Requirements

Did Not Meet Requirements

As indicated the well was drilled and is functional as of October 2010. At the current rate of production it is anticipated that overburden removal on Pits 13, 14 and 15 will occur in the second half of 2013. As the well is installed and functional, if necessary, it will be used as a
Operator Comments
overburden removal on pits 13, 14 and 15 occurs. Reports: Report status of well and target date for overburden removal in annual report. Citation: MRP, Volume 7, Chapter 7, Section 731.530, page 7-59
Status: Well was drilled October of 2010, but its function as a water replacement well will not occur until
removal for Pits 13, 14 and 15. Frequency: One time, when needed
Title: WATER REPLACEMENT WELL Objective: Alton Coal Development, LLC commits to having the water-replacement well (or other appropriate water replacement source as approved by the Division) drilled and developed before beginning overburden
Reviewed by Ingrid Campbell 6/26/12: The logs of the wildlife protection and safety meetings were provided in the report.
Reviewer Comments
Two wildlife awareness discussions were given with Coal Hollow Mine employees in 2011, logs of these meetings are included. There were no road kills of deer, elk, sage-grouse or domestic livestock at the mine site or between the mine and highway 89 by Coal Hollow Mine Employees.
Operator Comments .
heavy equipment. Frequency: Continuous and as needed for new employees throughout the life of the mine. Status: Ongoing from the onset of mining activities. Reports: Annual, log of employee awareness meetings, road kills for deer, elk, sage grouse and domestic livestock from the mine site to highway 89. Citation: MRP, Volume 2, Chpater 3, pages 3-54, 55.
Title: WILDLIFE AWARENESS PROGRAM Objective: To provide protection for the resident wildlife and minimize impacts (dollisions) from vehicles and
not included in the annual report. Please include that report in the annual report in the future.
Reviewed by Ingrid Campbell 6/26/12: Copy of contract is located in addendum 3-5 of the MRP. The 2011 report from Kevin Dustin is

water replacement well.

				,
Reviewer Comments	\boxtimes	Met Requirements		Did Not Meet Requirements
Reviewed by Ken Hoffmar	June	21: as stated overburden removal	l on Pits 13, 14, ar	nd 15 has not yet occurred so requirements are met.
			*	
Objective: To reestabl Frequency: Annual su Status: Ongoing, radio Reports: Annual sumr Citation: MRP, Volume	ish co mma colla nary i	ry of work completed. ared birds have been using t	on and near by the corridor in	Hoyt's Ranch sage grouse populations.
Operator Comments				
Approximately 155 acres of corridor and monitoring he Appendix 3-6 of the MRP.	of addi ave be	tional corridor improvement was en included in the "Greater Sage-	completed in 20° grouse Populatio	11. Additional information regarding the connectivity on and Habitat Improvement - Progress Report" in
Reviewer Comments	\boxtimes	Met Requirements		Did Not Meet Requirements
		and habitat improvement progre • MRP (tasks 4000, 4039 and 4100		ndix 3-6 of the MRP is currently under review by the

Frequency: Annual su: Status: Ongoing. The area needs to be surve Reports: Annual sumn	and d mmai perm yed fo nary o	evelop a 72 acre parcel of sary y until complete	noted in the M sh and species	IRP and correspondence. The completed
Operator Comments				
too dense for sage-grouse	use) o comple	f which approximately 2.5 acres veted in 2011 and results are inclu-	vere treated by di	40 acres of intact dense sagebrush (considered to be sking and planting in 2010. The initial survey of the er Sag-grouse Population and Habitat Improvement -

Reviewer Comments 🖂	Met Requirements		Did Not Meet Requirements
	n and habitat improvement progres ne MRP (Tasks 4000, 4039, and 4100		ndix 3-6 of the MRP is currently under review by the
Objective: To reduce raptor Frequency: Annual summary Status: Ongoing, work con Reports: Annual summary	IPER TREES WITHIN KEY HA or perches and increase sage ary of utilization for nesting a npleted in 2006. of utilization for nesting and hapter 3, Appendix 3-5, page	grouse habitat nd brood reari brood rearing	t. ing.
Operator Comments			
2011 vegetation surveys were c	ompleted to assess success of the v	vegetation treatm	ocus of additional sagebrush treatments in 2010. In nent. Wildlife use was looked for but not observed in eadow area immediately east of this treatment area
Reviewer Comments	Did Not Meet Requiremen	ts 🖂	Met Requirements
brooding and nesting. The 201 improvement work done be Alt	1 vegetation surveys were not inclu	uded in the repor	for the summary of the utilization of key habitats for t. Appendix 3-5 and 3-6 summarize the habitat lamation projects. These appendices are currently
Frequency: Annually durin Status: Ongoing each sprir Reports: Annual summary	to an alternate lek during act og spring ng during active mating perio of work completed to date. hapter 3, Appendix 3-5, page	ods.	erations.
Operator Comments			
In 2011 there was no attempt to began a program in 2012 with t will be mined in 2014.	attract birds to an alternate site, w he direction of Dr. Petersen to fulfil	vith better clarific II this commitmer	ation of the requirement of this comment, ACD has nt. Currently it is anticipated that the traditional lek

Did Not Meet Requirements

Reviewer Comments 🛛

Met Requirements

		16
Reviewed by Ingrid Campbell 6/28/2012: As stated above, due to a misunderstanding Violation # 10092 was issued by the Division to Alton Coal Company on December 5, the monitoring program for 2012 and NOV 10092 was terminated on June 20, 2012.	g, the lek was not monitor , 2011. Alton Coal compar	ed in 2011. Notice of ny is currently planning
Title: RECLAMATION TIMETABLE Objective: To ensure timely reclamation Frequency: No more than 40 acres to be disturbed at any given time. Status: Ongoing, once reclamation begins (no more than 40 acres distu	urbed at a time)	
Reports: Annual summary of work completed to date. Citation: MRP, Volume 2, Chapter 3, page 56	arbed at a time).	
Operator Comments		
The initial area to begin reclamation (the west end of the spoils pile) is approaching t be planted in the spring of 2012.	the permitted final form. I	t is anticipated that it will
Reviewer Comments Did Not Meet Requirements 🖂	Met Requirements	
Reviewed by Priscilla Burton on 6/28/2012. There are two commitments in the MRP 1 first provided under R645-301-341.100 (Chap 3, p. 56) states, "No more than 40 acres This requirement is more specifically described in the second reclamation commitme (Chap 5, p. 5-59) which states, "Generally, mined areas will be backfilled and graded with the commitment of the commitmen	will be disturbed at one ti ent provided under R645-3	me for mining." 301-542.100 through 600

Reviewed by Priscilla Burton on 6/28/2012. There are two commitments in the MRP that pertain to contemporaneous reclamation. The first provided under R645-301-341.100 (Chap 3, p. 56) states, "No more than 40 acres will be disturbed at one time for mining." This requirement is more specifically described in the second reclamation commitment provided under R645-301-542.100 through 600 (Chap 5, p. 5-59) which states, "Generally, mined areas will be backfilled and graded within approximately 60 days following coal removal, or 1,500 feet of active coal removal face." This latter commitment echoes the requirements for Surface Mining Backfilling and Grading outlined in R645-301-553. Figure 7 of the 2011 Annual Report shows Pits 1 & 2 were backfilled in 2011. These pits will eventually be buried under the spoil pile. Figure 7 also shows mined out pit 3, and the area exposed, blasted and mined in pit 5. Inspection reports #3082 and #3146 confirm that at present, Pit 4 is being actively mined, Pit 3 has been backfilled and Pit 5 is being backfilled. Each pit is approximately 500 ft wide and 1,000 ft. long (approximately 11.5 acres) as shown on Dwg. 5-10. The operation is in compliance with R645-301-553.

FUTURE COMMITMENTS AND CONDITIONS

The following commitments are not required for the current annual report year, but will be required by the permittee in the future as indicated by the "status" field. These commitments are included for information only, and do not currently require action. If you feel that the commitment is no longer relevant or needs to be revised, please contact the Division.

included for information only, and do not currently require action. If you feel that the
commitment is no longer relevant or needs to be revised, please contact the Division.
Title: REVIEW AND EVALUATE THE FACILITIES SPILL PLAN (APPENDIX 7-5)
Objective: To ensure the accuracy of the Facilities Spill Plan and to determine if additional or more effective spill
prevention and control technology that is applicable to the facility must be added.
Frequency: At least once every five years.
Status: Pending, next review due 2014.
Reports: Completed Plan Review form submitted for incorporation into Appendix B of Appendix 7-5.
Citation: MRP, Volume 7, Chapter 7, Appendix 7-5, Section 2.2 PLAN REVIEW, page 2.
T'.L. DECTORATION OF LEW
Title: RESTORATION OF LEK Objective: To restore the original lek at the end of mining activities.
Frequency: Once
Status: Restoration of the lek will begin at final reclamation.
Reports: Annual summary of work completed after reclamation begins.
Citation: MRP, Volume 2, Chapter 3, Appendix 3-5, page 12.
Citation. With , Volume 2, Chapter 3, Appendix 3 3, page 12.
Title: SAGE GROUSE MONITORING
Objective: To monitor the population densities at the Hoyt's ranch and Alton leks and migration patterns in between as long as the birds are living.
Frequency: Annual summary
Status: Ongoing, meet with the Division six months prior to mining through the lek to discuss minimizing impacts
to sage grouse.
Reports: Annual Summary of work completed.
Citation: MRP, Volume 2, Chapter 3, Appendix 3-5, page 13.
OPERATOR COMMENTS (OPTIONAL)
REVIEWER COMMENTS

.

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

lease list attachments	:		
	•		
eviewer Comments			

MAPS

Copies of mine maps, current and up-to-date through at least December 31, 2011, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

		Incl	Included		Confidential	
Map Name	Map Number	Yes	No	Yes	No	
Annual Mine/ Reclamation Area Map					\boxtimes	
					\boxtimes	
Reviewer Comments 🖂 Met Requirements 🗌 [Did Not Meet Requirements			
Man chave music sticks for 2 years or life of min a sta	ha museanthy amproved status					
Map shows projections for 3 years or life of mine at t	ne presentiy approved status.					